Community: WARWICK, CITY OF Community No: 445409

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

1. LOMCs Incorporated

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
102	99-01-051P	11/24/2000	PAWTUXET RIVER - WARWICK WWTF EARTHEN FLOOD CONTAINMENT DIKE	4454090002D	44003C0127G

2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	93-01-294A	02/04/1993	45 PEQUOT AVENUE	4454090006E	44003C0134G
LOMR-F	97-01-196A		RIVERDALE ESTATES - LOTS 11 AND 12 - 72 BLUFF AVE.	4454090006E	44003C0132G
LOMA	98-01-684A		40 SHAWOMET AVENUE - ASSESSORS MAP 333, LOT 235	4454090006E	44003C0151G
LOMA	99-01-688A		HARBOR VIEW ESTATES, 200CHANNEL VIEW RD.	4454090009D	44003C0142G
LOMA	99-01-1074A	09/24/1999	ASSESSORS MAP 340 - LOT 675 - 226 STILLWATER DRIVE	4454090006E	44003C0133G
LOMA	00-01-0430A	04/04/2000	17 TIDEWATER DRIVE	4454090006E	44003C0134G
LOMA	01-01-0984A	08/24/2001	109 AMORE ROAD	4454090005E	44003C0141G
LOMA	02-01-0730A	03/20/2002	127 TEA HOUSE LANE	4454090009D	44003C0142G

4/23/2009 Page 1 of 4

Community: WARWICK, CITY OF Community No: 445409

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	02-01-1316A	07/03/2002	PLAT 285, LOT 30417 O'KEEFE LANE	4454090003E	44003C0014G
LOMA	02-01-1478A	08/07/2002	295 RANDALL AVENUE	4454090009D	44003C0142G
LOMA	03-01-0188A	01/30/2003	4 RAILROAD ROW	4454090002D	44003C0126G
LOMA	03-01-0894A	04/07/2003	60 SEA VIEW DRIVE	4454090006E	44003C0134G
LOMA	04-01-0750A	03/08/2004	44 JUNIPER AVENUE	4454090005E	44003C0129G
LOMA	04-01-0752A	03/18/2004	139 SECOND POINT ROAD	4454090006E	44003C0134G
LOMR-F	04-01-0390A	04/19/2004	HERFF JONES DEVELOPMENT150 HERFF JONES WAY	4454090003E	44003C0018G
LOMA	04-01-1232A	07/12/2004	LOT 3 105 EDYTHE STREET	4454090006E	44003C0134G
LOMA	05-01-0483A	08/23/2005	15 EMERSON AVENUE PLAT 331, LOT 75	4454090006E	44003C0132G
LOMA	05-01-0800A	09/20/2005	ELM BROOK MANOR, LOT 23 100 ELMBROOK DRIVE	4454090006E	44003C0134G
LOMA	06-01-0089A	01/05/2006	13 PRIMROSE DRIVE	4454090008F	44003C0141G
LOMA	07-01-0431A	02/20/2007	BROOMFIELD PLAT, LOT 2 8 MELBOURN AVENUE (RI)	4454090005E	44003C0129G
LOMA	07-01-1102A	08/16/2007	LOT 49 & 50, GREEN ACRES83 ALPINE STREET	4454090006E	44003C0134G
LOMA	07-01-1007A	08/28/2007	1755 BALD HILL ROAD	4454090004D	44003C0109G
LOMA	08-01-0271A	02/26/2008	422 LAKE SHORE DRIVE - LOT 14, LAKE VIEW TERRACE	4454090006E	44003C0131G
LOMA	08-01-0755A	05/27/2008	1522 WEST SHORE ROAD	4454090006E	44003C0134G
LOMA	08-01-0830A	05/29/2008	BROOMFIELD PLAT, LOT 1 20 MELBOURNE ROAD	4454090005E	44003C0129G

4/23/2009 Page 2 of 4

Community: WARWICK, CITY OF Community No: 445409

3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
			NO CASES RECORDED	

- 1. Insufficient information available to make a determination.
- 2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
- 3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
- 4. Revised hydrologic and hydraulic analyses.
- 5. Revised topographic information.

4. LOMCs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	199301036D&D	02/14/1985	PLAT 279 LOT 38 AND PLAT 280 LOT 5		44003C0000G
LOMA	195100332D&D	05/06/1988			44003C0000G
LOMA	195100333D&D	12/20/1989			44003C0000G
LOMA	199201718R01	09/21/1992		0006E	44003C0000G
LOMA	199300113R01	09/30/1992		4454090006E	44003C0000G
LOMR-F	199500020R01	11/28/1994			44003C0000G
LOMA	199600036R01	04/09/1996		4454090006E	44003C0000G

4/23/2009 Page 3 of 4

Community: WARWICK, CITY OF Community No: 445409

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	199600061R01	04/18/1996		4454090005E	44003C0000G
LOMA	199600166R01	07/23/1996		4454090006E	44003C0000G
LOMA	199600224R01	09/16/1996		4454090006E	44003C0000G
LOMR-FW	07-01-0070A	03/20/2007	PONTIAC MILLS Knight Street (RI)	4454090002D	44003C0000G

4/23/2009 Page 4 of 4